Owner Name and Address: Debbie St Pierre PO Box 3069 Box Elder MT 59521 Phone: (406) 395-4300

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2106215	Village Grocery	Mile Marker St	Box Elder	59521	(406) 395-4300

TankiD/Alt TankiD Ta Status Num	•	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01	4/30/1978	Gasoline	Asphalt Coated or Bare Steel	Galvanized Steel	Not Listed	ABCDEFGHIJK•	Yes
Temporarily Out of Use	28 / No	8,000	Lined Interior	None		B DEFGHIJK•	No No No
2 / 02	4/30/1978	Gasoline	Asphalt Coated or Bare Steel	Galvanized Steel	Not Listed	(ABCDEFGHIJK)	Yes
Temporarily Out of Use	28 / No	6,000	Lined Interior	None		B DEFGHIJK)	No No No

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed	

Report Generation Date: 7/3/2006 Page 1 of 22

Owner Name and Address: Kremlin Farmers Union Oil Company PO Box 110 Kremlin MT 59532 Phone: (406) 390-1615

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2105421	Farmers Union Oil Co Gildford	5th St	Gildford	59525	(406) 376-3248

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
12 / S12 Currently In Use	979	7/1/1999 07 / Ye	Gasoline 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIJEL  B DEFOHIJEL	Yes Yes Yes Yes
13 / S13 Currently In Use	980	7/1/1999 07 / Ye	Gasoline 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	8 DEF9H1J&L	Yes Yes Yes Yes
14 / S14 Currently In Use	981	7/1/1999 07 / Ye	Diesel 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<b>ABCDEFGHJØL B DEF H J K L</b>	Yes Yes Yes Yes
15 / S15 Currently In Use	982	7/1/1999 07 / Ye	Diesel 15,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGH1J&L B DEF@H1J&L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 22

Owner Name and Address: BNSF Railway 2650 Lou Menk Dr Second Floor Fort Worth TX 76131 Phone: (817) 333-2000

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
1109528	BN Glendive Fueling Facility	235 Main St	Havre	59501	(406) 265-0483	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / SKC1 Currently in Use	505	9/1/1991 14 / Ye	Diesel 680,000	Epoxy Coated Steel None	Fiberglass Reinforced Plastic Double-Walled	Gravity Feed	(ABCDEFGHIJEL B DEFOHIJKL	Yes Yes Yes Yes
12 / 03 Currently in Use	504	12/28/1989 16 / No	Mixture 16,000	STI-P3 Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Gravity Feed	(ABCDEF.H)J(K) B DEF.H)J(K)	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 22

Owner Name and Address: Havre Public Schools PO Box 7791 Havre MT 59501 Phone: (406) 265-9032

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2100022	Havre School Bus Garage	1395 11th St W	Havre	59501	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	1290	11/1/1988 17 / No	Diesel 12,000	STI-P3 None	Bare Steel Cathodically Protected	U.S. Suction	<b>ABCD●● GH J K L B E F G H J K L</b>	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 22

Owner Name and Address: Ellis Enterprises Inc 1230 11th St Havre MT 59501 Phone: (406) 265-6454

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2100088	Short Stop Havre	1639 5th AVE	Havre	59501	(406) 652-5323

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3862	12/31/1971 34 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	<pre>A • • D E F G H   J K L</pre> • • E F G H   J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	3863	12/31/1971 34 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	(A) (D) (B) (B) (B) (B) (B) (B) (B) (B) (B) (B	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 5 of 22

Owner Name and Address: Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2100089	Kum and Go Store 892	911 11th St W	Havre	59501	(406) 265-9821

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3551	12/31/1971 34 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	ABC • E F G H 1 J K L  B • E F G H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	3552	1/1/1972 34 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJK) (BOEFGHIJK)	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	<b>K</b> Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 22

Owner Name and Address: Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2100103	Kum and Go Store 893	1004 1st St	Havre	59501	(406) 265-9812

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3729	2/18/1972 34 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Impressed Current	Pressurized	<b>ABCDEFGH●JKL ● ●EFGH●JKL</b>	Yes Yes Yes Yes
2 / 02 Currently in Use	3730	2/18/1972 34 / No	Diesel 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Impressed Current	Pressurized	<ul><li>● E F G H ● J K L</li></ul>	Yes Yes Yes Yes
3 / 03 Currently in Use	3731	2/18/1972 34 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic Impressed Current	Pressurized	ABCDEFGH•JKL  • • EFGH•JKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 7 of 22

Owner Name and Address: Stromberg Enterprises Inc PO Box 608 Havre MT 59501 Phone: (406) 265-2824

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2102166	Strombergs Sinclair	1200 1st St	Havre	59501	(406) 265-3441

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
8 / 08 Currently In Use	3965	3/1/1999 07 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B         DEF         HIJKL	Yes Yes Yes Yes
9 / 09 Currently In Use	3966	3/1/1999 07 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEFOHIJKL	Yes Yes Yes Yes
10 / 10 Currently In Use	3967	3/1/1999 07 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	8 0 6 F 6 H 1 J K L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 8 of 22

Owner Name and Address: Doug Heltne 140 1st St Havre MT 59501 Phone: (406) 265-4346

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2106481	Heltnes Service Center	140 1st St	Havre	59501	(406) 265-4346	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 05 Currently In Use	1736	7/20/1998 07 / No	Gasoline 2,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • E F G H   J K L   B D E F G H   • K L	Yes Yes Yes Yes
6 / 06 Currently In Use	1737	7/20/1998 07 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	(ABCOEFGH)JKL (B DEFGH)OKL	Yes Yes Yes Yes
7 / 07 Currently In Use	1738	7/20/1998 07 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABC • E F G H I J K L B D E F G H I • K L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 9 of 22

Owner Name and Address: Cenex Supply & Marketing PO Box 990 Havre MT 59501 Phone: (406) 265-2296

Sys Fac I	Location Name	Location Street Address	Location (	City Zip	Location Phone	
2107467	Cenex Supply & Marketing Havre	5 1st St	Havre	59501	(406) 265-2296	_

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
8 / 08 Currently In Use	<b>538</b> 6/1/1997 09 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes
9 / 09 Currently In Use	<b>539</b> 6/1/1997 09 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B	Yes Yes Yes Yes
10 / 10 Currently In Use	<b>540</b> 6/1/1997 09 / No	Gasohol 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes
11 / 11 Currently In Use	<b>541</b> 6/28/1997 09 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes
12 / 12 Currently In Use	<b>542</b> 6/28/1997 09 / No	Gasohol 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes
13 / 13 Currently In Use	<b>543</b> 6/1/1997 09 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL         B OEFOHIJKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 10 of 22

Owner Name and Address: Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2108068	Holiday Stationstore 272	200 1st St W	Havre	59501	(406) 265-8421

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3013	10/1/1985 20 / No	Gasoline 12,000	STI-P3 Impressed Current	Bare Steel Impressed Current	Pressurized	(ABCOEFGHI)(%L) (O) (E) (E) (H) (I) (K) (L)	Yes Yes Yes Yes
2 / 02 Currently in Use	3014	10/1/1985 20 / No	Gasoline 12,000	STI-P3 Impressed Current	Bare Steel Impressed Current	Pressurized	(ABCOEFGHUJKL) (DEFGHUJKL)	Yes Yes Yes Yes
3 / 03 Currently in Use	3015	10/1/1985 20 / No	Gasoline 10,000	STI-P3 Impressed Current	Bare Steel Impressed Current	Pressurized	ABCOEFGHIJKL  • • EFGHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	3016	10/1/1985 20 / No	Diesel 10,000	STI-P3 Impressed Current	Bare Steel Impressed Current	Pressurized	ABCOEFGHIJKL  • • EFGHIJKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 11 of 22

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2108705	Town Pump Inc Havre	136 1st St W	Havre	59501	(406) 265-9577

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently in Use	2472	11/15/1989 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	8	Yes Yes Yes Yes
4 / 04 Currently in Use	2473	11/15/1989 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC • EFGH   J   K   L	Yes Yes Yes Yes
5 / 05 Currently in Use	2474	11/15/1989 16 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC●EFGH().KL B ● EFGH().KL	Yes Yes Yes Yes
6 / 06 Currently in Use	2475	11/15/1989 16 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABC • E F G H   J K L   B • E F G H   J K L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 22

Owner Name and Address: Burlington Northern Railroad 235 Main St Havre MT 59501 Phone: (406) 265-0483

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2109548	BN Havre WWTP	235 Main St	Havre	59501	(406) 265-0483

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / 22 Currently in Use	506	6/21/1993 13 / No	Used Oil 20,000	Cathodically Protected Steel Double-Walled	No Piping None	Not Listed	ABCOEFOHIJKL B DEFGHIJKL	Yes Yes Yes Yes
17 / S23 Currently In Use	4877	1/22/2004 02 / Ye	Diesel 640,000	Concrete None	Galvanized Steel Cathodically Protected	Pressurized	(ABCDEFGH)J®L (B DEFGH)J&	Yes Yes Yes Yes
18 / S24 Currently In Use	4878	1/22/2004 02 / Ye	Diesel 640,000	Concrete None	Galvanized Steel Cathodically Protected	Pressurized	(ABCDEFGH)J&L B DEFGH)J&	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 13 of 22

Owner Name and Address: Ezzies Wholesale Inc PO Box 1770 Malta MT 59538 Phone: (406) 654-2331

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2112751	Ezzies Wholesale Havre	726 1st St W	Havre	59501	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 06 Currently in Use	883	7/1/1992 14 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	B	Yes Yes Yes Yes
2 / 07 Currently in Use	884	7/1/1992 14 / No	Diesel 12,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	\( \begin{align*} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	Yes Yes Yes Yes
3 / 05 Currently in Use	882	7/1/1992 14 / No	Gasoline 12,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH) O (K) (B) (E) F (G) H) (J) (K)	Yes Yes Yes Yes
4 / 08 Currently in Use	885	7/1/1992 14 / No	Diesel 12,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH) OKL (BOEFGH) OKL	Yes Yes Yes Yes
5 / 01 Currently in Use	878	7/1/1992 14 / No	Hazardous 4,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABC • E F G H ] • K L B • E F G H ] • K L	Yes Yes Yes Yes
6 / 02 Currently in Use	879	7/1/1992 14 / No	Other 12,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH)OKL (BOEFGH)OKL	Yes Yes Yes Yes
7 / 03 Currently in Use	880	7/1/1992 14 / No	Gasoline 12,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABC • E F G H   • K L B • E F G H   • K L	Yes Yes Yes Yes
8 / 04 Currently in Use	881	7/1/1992 14 / No	Gasoline 12,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	(A) B) (C) (E) (F) (G) (H) (D) (K) (L)	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 14 of 22

Owner Name and Address: Bill Dritshulas PO Box 1430 Havre MT 59501 Phone: (406) 265-8861

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2112763	Emporium Food & Fuel	1415 1st St	Havre	59501	(406) 265-8861	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	2971	8/1/1992 13 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
2 / 02 Currently in Use	2972	8/1/1992 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes
3 / 03 Currently in Use	2973	8/1/1992 13 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABC●EFGH())(KL) B ● EFGH()(KL)	Yes Yes Yes Yes
4 / 04 Currently in Use	2974	8/1/1992 13 / No	Gasoline 6,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABC • E F G H   J K L   B • E F G H   J K L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 15 of 22

Owner Name and Address: Hill County Courthouse 315 4th St Havre MT 59501 Phone: (406) 265-5481

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5613886	Hill County Justice Center	1450 2nd St W	Havre	59501		

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently In Use	<b>1377</b> 7/20/1998 07 / Ye	Diesel 2,000	Concrete None	Bare Steel Double-Walled/Non-Corro	Pressurized	ABCDEFGHIOKL  B DEFOHIJKL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 16 of 22

Owner Name and Address: Hingham Motors PO Box 228 Hingham MT 59528 Phone: (406) 397-3194

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2100783	Hingham Motors	Central Ave & 1st St N	Hingham	59528	(406) 397-3217	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / S06 Currently in Use	1383	7/25/1995 10 / Ye	Diesel 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGHIJ®L B DEF®HIJ®L	Yes Yes Yes Yes
7 / S07 Currently In Use	1384	10/1/1998 07 / Ye	Gasoline 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGH) (BC) (B (DEFGH) (RC)	Yes Yes Yes Yes
8 / S08 Currently In Use	1385	10/1/1998 07 / Ye	Gasoline 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGH)J&L (B DEF•H)J&L	Yes Yes Yes Yes
9 / S09 Currently In Use	1386	10/1/1998 07 / Ye	Diesel 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGH)J.L B (DEF.H)J.R.L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 17 of 22

Owner Name and Address: Fraser Oil Inc PO Box 770 Inverness MT 59530 Phone: (406) 292-3833

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2107327	Fraser Oil Inc Inverness	US Highway 2	Inverness	59530	(406) 292-3833

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently in Use	1120	10/15/1992 13 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABCOEFGHIJKL B DEFGHIJKO	Yes Yes Yes Yes
5 / 05 Currently in Use	1121	10/15/1992 13 / No	Diesel 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	<b>ABC●EFGHIJKL B DEFGHIJK●</b>	Yes Yes Yes Yes
6 / 06 Currently in Use	1122	10/15/1992 13 / No	Gasoline 1,000	STI-P3 None	Fiberglass Reinforced Plastic None	Safe Suction	ABCOEFGHIJKL B DEFGHIJKO	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 18 of 22

Owner Name and Address: Bank of New York and Trustee 101 Barclay St 12 New York NY 10286 Phone:

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614084	Craig & Bonnie Fraser	100 3rd St W	Inverness	59530	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	0	/ No	Gasoline 1,100	Asphalt Coated or Bare Steel None	Bare Steel None	Not Listed	ABCDEFGHIJKO B DEFGHIJKO	No No No No
2 / 02 Currently In Use	0	/ No	Gasoline 1,100	Asphalt Coated or Bare Steel None	Bare Steel None	Not Listed	ABCDEFGHIJKO B DEFGHIJKO	No No No No

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	<b>K</b> Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 19 of 22

Owner Name and Address: Kremlin Farmers Union Oil Company PO Box 110 Kremlin MT 59532 Phone: (406) 390-1615

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2110030	Farmers Union Oil Co Kremlin	110 Main St	Kremlin	59532	(406) 372-3248

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently in Use	983	1/16/1972 34 / Ye	Gasoline 10,000	Asphalt Coated or Bare Steel None	Flexible Plastic Double-Walled	Pressurized	ABCDEFGH1J&L B DEF•H1J&L	Yes Yes Yes Yes
2 / S2 Currently in Use	984	1/16/1972 34 / Ye	Gasoline 15,000	Asphalt Coated or Bare Steel None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGH))(L) (B DEF(H))(K)	Yes Yes Yes Yes
3 / S3 Currently in Use	985	1/16/1975 31 / Ye	Diesel 15,000	Asphalt Coated or Bare Steel None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGH)JOL B (DEFOH)JOL	Yes Yes Yes Yes
4 / S4 Currently in Use	986	1/16/1976 30 / Ye	Diesel 15,000	Asphalt Coated or Bare Steel None	Flexible Plastic Double-Walled	Pressurized	(ABCDEFGH)J.L B (DEF.H)J.KL	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 20 of 22

Owner Name and Address: Toners Tire Rama PO Box 266 Rudyard MT 59540 Phone: (406) 355-4131

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone	
2102475	Toners Tire Rama	103 Main St	Rudyard	59540	(406) 355-4131	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 05 Currently In Use	2108	11/1/1997 08 / No	Diesel 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	AB • • E F G H 1 J K L  B D E F G H 1 • K L	Yes Yes Yes Yes
6 / 06 Currently In Use	2109	11/1/1997 08 / No	Gasoline 2,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Safe Suction	(A B • • E F G H ) J (K L) (B D E F G H ) • (K L)	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 21 of 22

Owner Name and Address: Farmers Union Oil Co Rudyard PO Box 290 Rudyard MT 59540 Phone: (406) 355-4543

Sys Fac I	Location Name	Location Street Address	<b>Location City</b>	Zip	Location Phone
2103509	Farmers Union Oil Co Rudyard	1 Main St	Rudyard	59540	(406) 355-4543
		PO Box C			

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / S4 Currently in Use	947	4/23/1966 40 / Ye	Diesel 2,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	(ABCDEFGHIJC) (B DEFOHIJC)	Yes Yes Yes Yes
5 / S5 Currently in Use	948	4/23/1966 40 / Ye	Gasoline 10,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCDEFGHIJ&L B DEF•HIJ&L	Yes Yes Yes Yes
6 / S6 Currently in Use	949	4/23/1966 40 / Ye	Gasoline 5,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic Double-Walled	Pressurized	(ABCDEFGH)J.L B (DEF.H)J.K.L	Yes Yes Yes Yes

## Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 22 of 22